



-2-

D. PHYSICAL DEGRADATIONS

1. SR SIDE: SEVERAL PROCESSING STREAKS ARE PRESENT FROM FRAME 1150 TO THE END.

2. BOTH SIDES: NINE HEAT SPLICES AND ONE MANUFACTURER'S SPLICE ARE PRESENT ON EACH OF THE SIDES.

E. AUXILIARY DATA: THE FRAME COUNTER FAILED TO REGISTER FOUR TIMES DURING THE MISSION. ALL OTHER DATA RECORDING SYSTEMS FUNCTIONED PROPERLY.

4. POSITIVES: PRINTING AND PROCESSING ARE GOOD.

GP-1

S E C R E T

-- END OF MSG --

1

1